



eRAD RIS

# CUSTOMER RELEASE NOTES

Hotfix Build 4.2022.10.24.5

UPDATED MAY 25, 2023

# Table of Contents

<b>Summary</b> .....	<b>3</b>
Intended Audience.....	3
Release Content.....	3
Who Is Affected.....	3
<b>New Settings</b> .....	<b>4</b>
<b>New Features</b> .....	<b>5</b>
<b>Resolved Issues and Known Limitations</b> .....	<b>6</b>
Resolved Issues.....	6
New Known Limitations.....	6
<b>Version Details</b> .....	<b>7</b>
Package Contents.....	7
Code Stream.....	8
eRAD RIS Release Version Numbers.....	9

## Publication History

Revision	Author	Description
May 25, 2023	Kevin Brooks / Hilary Saltmarsh	<ul style="list-style-type: none"> <li>▪ Commercial release.</li> </ul>

# SUMMARY

## Intended Audience

The intended audience for this CUSTOMER RELEASE NOTES document is the RIS Administration team for all eRAD RIS customers.

The intent of this document is to describe the content of the build or hotfix with sufficient detail for a Customer to be able to understand the features, and for the Customer's RIS Administrator to be able to perform routine configuration of features.

This information should be used by all customers to determine how these changes affect their organization's workflow, and to plan their organization's upgrade strategy for eRAD RIS.



*There is no separate SERVICE RELEASE NOTES edition of this document.*

## Release Content

*This hotfix release of ERAD RIS 4.2022.10.24.5 resolves issues refreshing worklists and multiple Hebrew localization display issues.*

## Who Is Affected

This version is recommended to be applied on ERAD RIS v4.2022.10.24 and V4.2022.10.24.X installations.

# NEW SETTINGS

No settings were added or updated with this release.

# NEW FEATURES

No new features were introduced with this release.

# RESOLVED ISSUES AND KNOWN LIMITATIONS

## Resolved Issues

This release resolves the following issues:

Redmine #	Subject
27273	<b>This is a service-only change with no customer-facing functionality.</b>
33726	Resolved localization issue on the Walk-In screen where fields on the Exam tab were not respecting right-to-left layout.
33727	Resolved localization issue where Indication and Other Reason for Study controls were not respecting right-to-left layout.
33831	Resolved localization issue where Patient Notes controls were not respecting right-to-left layout.
33836	Resolved localization issue on the Scheduling Screen where the Exam tab was not respecting right-to-left layout.
33848	Resolved Worklists issue where worklists and the patient folder were not automatically refreshing after cancelling a study.

## New Known Limitations

No new known limitations were identified with this release.

# VERSION DETAILS

## Package Contents

The release package includes the following folders:

---

## Code Stream

The following source code branches have been merged into this release:

LEGEND:

Light Green = Previously Released software

Gray = Internal version, non-release version

Bright Green = Current Release



*Note that the functionality of this release has not yet been merged forward into any other release.*

*Please carefully review the code stream diagram of any future releases before deploying to ensure that the functionality of this release will not be lost when upgrading.*



---

## eRAD RIS Release Version Numbers

The following table details the version identifiers for components in this release: